

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

467  
ENE  
1/2-1  
0.736 mi.  
3885 ft.

RESIDENCE  
7 BIRGHTON 3RD ROAD  
BROOKLYN, NY

NY Spills S106127300  
N/A

Relative:  
Higher

Actual:  
9 ft.

SPILLS:

Name: RESIDENCE  
Address: 7 BIRGHTON 3RD ROAD  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 0311080 / 2004-02-20  
Facility ID: 0311080  
Facility Type: ER  
DER Facility ID: 158398  
Site ID: 189816  
DEC Region: 2  
Spill Cause: Equipment Failure  
Spill Class: C4  
SWIS: 2401  
  
Spill Date: 2003-12-04  
Investigator: CESA WYER  
Referred To: Not reported  
Reported to Dept: 2003-12-29  
CID: 444  
Water Affected: Not reported  
Spill Source: Private Dwelling  
Spill Notifier: Other  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 2003-12-29  
Spill Record Last Update: 2004-04-26  
Spiller Name: MR. GLEICH  
Spiller Company: RESIDENCE  
Spiller Address: 7 BIRGHTON 3RD ROAD  
Spiller Company: 001  
Contact Name: MR. GLEICH  
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead\_DEC Field was SAWYER 2/20/04 - Sawyer - Called Paul Basso at Milro Assoc. and confirmed that they performed the clean up. He is sending receipt and waste manifest. Closed. 4/20/04 - Sawyer - Received Manifest and endpoint analysis."

Remarks: "LEAKING OIL TANK IN BASEMENT, ALL CLEANED UP AND REPAIRED. "

All Materials:

Site ID: 189816  
Operable Unit ID: 878850  
Operable Unit: 01  
Material ID: 499908  
Material Code: 0001A  
Material Name: #2 fuel oil  
Case No.: Not reported  
Material FA: Petroleum  
Quantity: 10.00  
Units: G  
Recovered: .00  
Oxygenate: Not reported